

In the Specification:

Please replace the paragraph beginning on page 29, line 25, with the following rewritten paragraph:

Bumps 28b are formed on the ends of the even number-th drain bus lines 16b on the upper end as viewed in FIG. 9. The bumps 28b are commonly connected to the drain connection line 34b through thin connection lines 36b.